

## Application: Patriot Launcher



### Problem

Assembly and disassembly was a serious problem with the current grease.

The parts become hot, causing the current grease to burn and the parts to seize.

### Environment

Hot, dusty and humid.

### Current product

G403 (Ministry of Defence grease)

### Solution

**Interflon HT1200**

NSN 8030-12-335-3965

### Result:

- No more seized parts.
- No irritation.
- Fewer maintenance hours.